

3937

Missing link pliers

- 2PVC handle
- Useful for removing and installing missing link

Dirt and corrosion may make it difficult to disassemble bike chain. Missing link pliers item 3937 provides a simple, immediate solution to such problem.

	art.	L mm	A mm	A1 mm	
039370010	3937	170	59	29	153

