

720FRD

Impact socket for Ford wheel nuts with aluminium damaged caps





Required when nut caps are damaged by impact wrenches

₩,	art.			
007200633	720FRD	18,5÷19,5	63	140









