

1482A/2

Wrench for tank floating ring nuts, 12 sectors



For operating on ring nut with no side slots installed on
Fiat and Ford cars and vans

500 g

