

1485TC

Tensioning lever for service belts, mounted on Ford, PSA, FCA engines

	art.	L mm	i
014850330	1485TC	475	680

