



**1485TC** Tensioning lever for service belts, mounted on Ford, PSA, FCA engines

	art.	L mm	
014850330	1485TC	475	680

