


1940E10/S...
Cinceles para martillos cincel 1940E10 Cortafrío plano Cortafrío para cortar y soltar chapa Butil de punta Cortafrío para puntos de soldadura y remaches

	art.	
019400040	1940E10/SN	1940 E10/SN-chisels for air hammers
019400041	1940E10/ST	1940 E10/ST-chisels for air hammers
019400042	1940E10/SD	1940 E10/SD-chisels for air hammers
019400043	1940E10/SPS	1940 E10/SPS-chisels for air hammers
019400044	1940E10/SDT	1940 E10/SDT-chisels for air hammers

