

**42AS**
**κλειδιά γερμανοπολύγωνα**

|  | art.        | MI<br>" | MI1<br>" | L<br>mm | H<br>mm | Ø<br>mm | S<br>mm | g   |
|---------------------------------------------------------------------------------|-------------|---------|----------|---------|---------|---------|---------|-----|
| 000421106                                                                       | 42AS 1/4    | 1/4     | 1/4      | 95      | 15,2    | 10,1    | 5,2     | 12  |
| 000421107                                                                       | 42AS 9/32   | 9/32    | 9/32     | 106     | 17,1    | 11,1    | 5,7     | 18  |
| 000421108                                                                       | 42AS 5/16   | 5/16    | 5/16     | 116     | 19      | 12,3    | 6,2     | 23  |
| 000421110                                                                       | 42AS 3/8    | 3/8     | 3/8      | 137     | 22,8    | 15,1    | 7,1     | 35  |
| 000421111                                                                       | 42AS 7/16   | 7/16    | 7/16     | 148     | 24,8    | 16,5    | 7,5     | 44  |
| 000421113                                                                       | 42AS 1/2    | 1/2     | 1/2      | 169     | 28,8    | 19,6    | 8,4     | 66  |
| 000421114                                                                       | 42AS 9/16   | 9/16    | 9/16     | 180     | 30,8    | 21      | 8,8     | 80  |
| 000421115                                                                       | 42AS 19/32  | 19/32   | 19/32    | 191     | 32,7    | 22,4    | 9,2     | 95  |
| 000421116                                                                       | 42AS 5/8    | 5/8     | 5/8      | 201     | 34,6    | 23,8    | 9,7     | 105 |
| 000421117                                                                       | 42AS 11/16  | 11/16   | 11/16    | 212     | 36,6    | 25,2    | 10,2    | 120 |
| 000421119                                                                       | 42AS 3/4    | 3/4     | 3/4      | 233     | 40,5    | 28      | 11,4    | 160 |
| 000421121                                                                       | 42AS 13/16  | 13/16   | 13/16    | 254     | 44,5    | 30,7    | 12,4    | 205 |
| 000421122                                                                       | 42AS 7/8    | 7/8     | 7/8      | 264     | 46,4    | 32,2    | 12,8    | 225 |
| 000421124                                                                       | 42AS 15/16  | 15/16   | 15/16    | 285     | 50,3    | 34,9    | 13,5    | 290 |
| 000421125                                                                       | 42AS 1      | 1x1     | 1x1      | 296     | 52,3    | 36,2    | 13,8    | 310 |
| 000421127                                                                       | 42AS 1.1/16 | 1,1/16  | 1,1/16   | 317     | 56,2    | 39      | 14,6    | 375 |
| 000421129                                                                       | 42AS 1.1/8  | 1,1/8   | 1,1/8    | 338     | 60,2    | 41,9    | 15,3    | 450 |
| 000421132                                                                       | 42AS 1.1/4  | 1,1/4   | 1,1/4    | 370     | 66      | 45,7    | 16,2    | 565 |
| 000421133                                                                       | 42AS 1.5/16 | 1,5/16  | 1,5/16   | 391     | 70      | 48,5    | 16,8    | 680 |
| 000421135                                                                       | 42AS 1.3/8  | 1,3/8   | 1,3/8    | 412     | 73,9    | 51,3    | 17,5    | 835 |
| 000421136                                                                       | 42AS 1.7/16 | 1,7/16  | 1,7/16   | 412     | 73,9    | 51,3    | 17,5    | 825 |
| 000421138                                                                       | 42AS 1.1/2  | 1,1/2   | 1,1/2    | 433     | 77,9    | 54      | 18,2    | 965 |

